

Product Information Bulletin: Life Liners- FH36 Firefighting Hood Voluntary recall

Life Liners: FH36 Hood

Batch number: 42453- March 2016

42675- May 2016

Possible Non Compliance:

Stanfield's has determined that some FH36 Firefighting hoods produced on production Lot# 42453, 42675, 161095 may not currently meet the requirements of NFPA 1971 with regards to the minimum hood side length of 9". (measurement indicated in blue on hood image). The Lot # can be located on the inner product label. Only products from Lot# 42453, 42675 and 161095 are affected by this notice. Approximately 360 units of product from these batches shipped to customers

Stanfield's has not received any reports of Injuries of failures of the product.

Stanfield's takes the safety of the members of the fire service seriously and is committed to continuous improvement to meet and exceed industry standards, and we are asking customers to return the affected product for replacement by contacting Stanfield's customer service at 902-895-5406 or your Life Liners distributor.

